ASC-TR-95-1006

# QUIC-LIFT™ LADDER ACCESS SYSTEM PRODUCT EVALUATION REPORT

AD-A286 854

Aeronautical Systems Center Weapons, Air Base and Range Product Support Office ASC/VXO 314 W. Choctawhatchee Ave., Suite 104 Ealin AFB, FL 32542-5717

31 October 1995

FINAL REPORT FOR PERIOD 15 AUG 1994 - 9 AUG 1995

26 2 22 012

96-00422

Distribution A: Approved for public release; distribution unlimited.

# **AERONAUTICAL SYSTEMS CENTER**

Air Force Material Command 
United States Air Force Eglin Air Force Base

#### NOTICE

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any employees, nor any of their contractors, subcontractors, or their employees, make any warranty, expressed or implied, or assume any legal liability or responsibility for the accuracy, completeness, or usefulness of any privately owned rights. Reference herein to any specific commercial product, process, or other service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency, contractor, or subcontractor thereof. The views and opinions of the authors expressed herein do not necessarily state or reflect those of the United States Government or any agency, contractor, or subcontractor thereof.

When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely Government-related procurement, the United States Government incurs no responsibility or any obligation whatsoever. The fact that the Government may have formulated or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication, or otherwise as in any manner construed, as licensing the holder, or any other person or corporation; or as conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

This technical report has been reviewed by the Public Affairs Office (PA) and is approved for public release; distribution is unlimited.

This report has been reviewed and is approved for publication.

FOR THE COMMANDER

WADE H. GRIMM Program Manager

Please do not request copies from the Aeronautical System Center, Weapons, Air Base and Range and Product Support Office (ASC/VXO). Address your request for additional copies to:

Defense Technical Information Center 8725 John J. Kingman Road Ft Belvoir, VA 22060-6218

If your address has changed, if you wish to be removed from our mailing list, or if your organization no longer employs the addressee, please notify ASC/VXO, 314 W. Choctawhatchee Ave., Suite 104, Eglin AFB FL 32542-5717, email: grimmw@eglin.af.mil, DSN 872-4695, ext 321, (904) 882-4695, ext 321 to help us maintain a current mailing list.

## REPORT DOCUMENTATION PAGE


NSN 7540-01-280-5500

Form Approved OMB No. 0704-0188

(4)

Public reporting burden for this collection of inform maintaining the data needed, and completing and suggestions for reducing this burden, to Washingto and to the Office of Management and Budget, Pap	reviewing the collect on Headquarters Ser	ion of information. Send c vices, Directorate for Inform	omments regarding the nation Operations and	us burden estimi	ate or any other :	aspect of this collection of information, including									
AGENCY USE ONLY (Leave blank)	, contract of the contract of	2. REPORT DATE 31 October 1995	giai, 50 2000.	<b></b>	RT TYPE AND DATES COVERED 5 Aug 1994 - 9 Aug 1995										
4. TITLE AND SUBTITLE QUIC-LIFT™ LADDER ACCESS	SYSTEM PRO	DDUCT EVALUAT	ION REPORT		5. FUNDING NUMBERS										
6. AUTHOR(S) Joseph Thompson, Wade H. Grimm, Stephen E. Kelley  7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) 89 SG/CEF Bldg 3464 Perimeter Road Andrews AFB, MD 20331-5000  9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) Aeronautical System Center					PE: 64708F  8. PERFORMING ORGANIZATION REPORT NUMBER  10. SPONSORING/MONITORING AGENCY REPORT NUMBER										
								Weapons, Air Base and Range, Product Support Office (ASC/VXO) 324 Choctawhatchee Ave., Suite 104 Eglin AFB, FL 32542-5717					ASC-TR-95-1006		
								1. SUPPLEMENTARY NOTES							
Za. DISTRIBUTION/AVAILABILITY STATEMENT					12b. DISTRIBUTION CODE										
Approved for public release; distribution is unlimited					A										
Final report of the commercial ted Ziamatic Corporation of Yardley, at Andrews AFB, Maryland betwe commercial off the shelf technolo and has been recommended for a	Pennsylvania en 15 Aug 19 gy for applica	. The evaluation v 94 and 9 Aug 199 tion to Air Force fi	vas conducted 5. This evalua refighting requ	by the 89 ition was pairements.	Support Gr art of a con The system	oup, Fire Protection Division atinuing program to explore									
			•												
	<del></del>				15. NUMBER	OF PAGES									
14. SUDJECT TERMS QUIC-LIFT™, ZICO, LADDER AC	CESS SYSTI	EM, LADDER LIF			15. NUMBER	55									

ŞAR Slandard Form 298 (Rev. 2-89) Prescribed by ANSI Std. 239-18





### DEPARTMENT OF THE AIR FORCE

AERONAUTICAL SYSTEMS CENTER (AFMC)

EGLIN AIR FORCE BASE, FLORIDA

31 Oct 95

MEMORANDUM FOR HQ AFCESA/CEXF

FROM: ASC/VXO

314 Choctawhatchee Ave., Suite 104

Eglin AFB, FL 32542-5717

SUBJECT: QUIC-LIFT™ Ladder Access System Product Evaluation Report

(Ref: Test Plan, July 1994)

- 1. <u>PURPOSE AND BACKGROUND</u>. The purpose of this test was to assess the effectiveness and suitability the ZICO QUIC-LIFT™ electrically actuated Ladder Access System manufactured by Ziamatic Corporation. The system tested is a pair of cast aluminum actuators that attach to the side of a first generation A/S32 P-22 structural firefighting vehicle. This unit is a standard option on the second generation P-22s currently being delivered to the Air Force. This evaluation w™ determine the feasibility of retrofitting the existing fleet of first generation P-22s in world wide firefighting duty. The QUIC-LIFT system is used to lower the side mounted aluminum ladders to a convenient height for safe and easy retrieval. The evaluation was managed by the 89 SG/CEF at Andrews AFB, Maryland between 15 Aug 94 and 9 Aug 95.
- 2. <u>SYSTEM DESCRIPTION</u>. The ZICO QUIC-LIFT™ System, is mounted on the horizontal surface above the side compartment of an A/S32 P-22 to provide convenient access to the standard side mounted ladders. The system consists of a pair of high-strength aluminum casting assemblies with Warner 12-volt linear actuators. The activation switch is mounted at ground level, where the operator can easily observe the entire operation. The actuators are powered by the vehicle's installed electrical system to raise and lower the ladders.
- 3. <u>METHOD</u>. New A/S32-P-22 pumper trucks are being delivered with an integrated ladder lift as standard equipment. The evaluation vehicle was an existing inventory first generation version of the P-22 that was modified by Kovatch Mobile Equipment (KME) to retrofit the ZICO QUIC-LIFT™ System for safe and convenient ladder access. The truck was then returned to service for evaluation on a daily basis.

- 4. <u>OBJECTIVES AND RESULTS</u>. The following objectives were used to assess operational effectiveness, compatibility, durability, stability, and suitability of the ZICO QUICLIFT™ system when employed on an A/S32 P-22 pumper truck.
- a. Objective E-1. Assess the effectiveness of the ladder access system to provide easy retrieval of the standard aluminum ladders during training and emergency response scenarios. The measure of effectiveness is accessibility of the ladders and other equipment from the side storage compartments. The criteria is not established. **Results**: The ladder lift was used during routine vehicle check-outs, training exercises, and actual fire response situations. In all reported use the operation was smooth and trouble free. When the truck was parked on an incline, the lift allowed lowering to the exact height needed. No problems accessing other equipment in side storage compartments was reported.
- b. Objective S-1. Assess the compatibility of the ZICO QUIC-LIFT™ system during installation on and operation of the P-22 under training and emergency response conditions. The measures of effectiveness are: no major vehicle modification to mount the system, and no hampering of normal operations. The criteria is not established. **Results**: The lift system was installed by KME using a diamondplate backing panel, eight bolts for each of the two lift mechanisms, and wiring the activation switch into the vehicle electrical system. The installation is relatively easy and could be accomplished from a kit at base level. The location on the right side of the P-22 will interfere at the lower limits with the auxiliary generator if it is extended as the ladder is lowered
- c. Objective S-2. Assess the durability of the ZICO QUIC-LIFT™ to function without failure throughout the ninety day evaluation for a minimum of 100 evolutions. The measure of effectiveness is serviceability of the ZICO QUIC-LIFT™ System. The criterion is that there should be no electrical failures, remote control failures, or binding during system operation. Results: The lift mechanism was formally evaluated during a 51 day period where it was evaluated for 45 documented evolutions. After this time, a new vehicle was delivered and the evaluation vehicle was placed in a reserve status, with only occasional use. Over the following year, whenever the vehicle was used as a substitute for primary vehicles down for maintenance, the system has operated flawlessly. Eight fire vehicles at Ft Rucker, Alabama have had ladder lift systems in operation for nearly five years with no repairs or replacement parts required.
- d. Objective S-3. Assess the durability of the P-22 structural integrity to support the ZICO QUIC-LIFT™ throughout the ninety day evaluation period. The measure of effectiveness is serviceability of the P-22. The criterion is that there should be no structural damage, loose rivets, cracks, or other indications of metal fatigue. **Results**: Since the evaluation began on 15 Aug 94, no structural fatigue or damage has been noted on the P-22 structure.

- e. Objective S-4. Assess the stability of the ZICO QUIC-LIFT™ when employed during training and emergency scenarios. The measure of effectiveness is serviceability and security of the ZICO QUIC-LIFT™ System. The criterion is that the unit should not bend, brake, or nosen at mounting locations during training or emergency operations. **Results**: The installed location of the two lift mechanisms results in more of the ladder weight being lifted by the rear mechanism. This was not a problem, the only result is that the front of the ladder raises quicker than the rear portion.
- f. Objective S-5. Assess the reliability, maintainability, and availability (RM&A) of the ZICO QUIC-LIFT™ system. The measure of effectiveness is serviceability of the system. The criterion is not established. **Results**: No maintenance has been required since the system was installed. The durability remarks under objective S-2 also apply to the reliability of the system, excellent.
- g. Objective S-6. Assess the installation and maintenance procedures prepared by Kovatch Mobile Equipment (evaluation vehicle modification contractor). The measure of effectiveness is sufficiency of detail in the instructions/diagrams provided. The criterion is that (1) the system can be installed as a local base level modification and (2) the system can be maintained at the base level without additional training. **Results**: The installation was completed at the KME facilities and detailed procedures were not provided. Engineering drawings of the location and equipment have been reviewed. If a field modification kit is prepared, an evaluation of installation by Air Force vehicle maintenance technicians should be accomplished.
- 5. CONCLUSIONS. The ZICO QUIC-LIFT™ system is a simple installation which is reliable and trouble free. The location on the right side of the P-22 will interfere at the lower limits with the auxiliary generator if it is pulled out as the ladder is lowered. If the rear lift mechanism can be located further aft, it would result in a more even distribution of ladder weight between the two lift mechanisms. Especially in off road scenarios, the ability to lower the ladder allows safe and easy retrieval.
- 6. <u>RECOMMENDATIONS</u>. An installation kit evaluation should be performed by Air Force vehicle maintenance technicians on a first generation P-22 and P-24 to validate a kit that would then be made available for upgrading the existing inventory of older pumper vehicles.

WADE H. GRIMM Program Manager

#### Attachment:

- 1. Product Illustration.
- 2. Distribution

1st Ind to ASC/VXO QUIC LIFT Ladder Access System Product Evaluation Report

HQ AFCESA/CEXF

18 Dec 95

Concur/non-consur with the recommendations in this report.

JAMES W HOTELL Chief, Fire Protection Division


#### QUIC-LIFT™ LADDER ACCESS SYSTEM


## The QUIC-LIFT™ System At-A-Glance

- (1) A close up view of one high-strength aluminum casting assembly. Assemblies come in sets of two.
- (2) The system in the storage position.
- (3) At the flick of a switch, the system lowers the ladder to a comfortable level for retrieval.

When in the storage position, ladders are out of the way, allowing essential storage space for other equipment.








The QUIC-LIFT™ Ladder Access System is an innovative concept in ladder storage and retrieval. At the flick of a control switch, the QUIC-LIFT™ system lowers any standard aluminum ladder to a convenient height for safe and easy retrieval. It minimizes the chance of back or shoulder injuries, while conserving the firefighter's energy for more critical tasks.

Comprised of two high-strength aluminum casting assemblies with Warner 12-volt linear actuators, the system is easy to install on the horizontal surface above the side compartment. Unlike other devices that extend far out from the apparatus, the QUIC-LIFT™ system remains close to apparatus when lowered.

The QUIC-LIFTTM system lowers ladders to a convenient position for retrieval, self-locking in any position. The switch operator can easily observe the entire operation.



## DISTRIBUTION

ASC-TR-95-1006

Eglin AFB offices: ASC/VXO AFDTC/PA WL/MNPM (Technical Library)	4 1 1	HQ AFRES/CEXF	4
Defense Technical Information Center Attn: DTIC-DDAC 8725 John J. Kingman Road Ft Belvoir, VA 22060-6218	2	Attn: Donald Warner 155 Second Street Robins AFB, GA 31098-1635	1
89 SG/CEF Attn: Mr Miland Young Bldg 3464, Fire Station #2 Perimeter Road	1	HQ AFSOC/CEF Attn: CMSgt Marshall 204 Bennett Ave. Hurlburt AFB, FL 32544-5270	1
Andrews AFB, MD 20331-5000		HQ AFSPC/CEPX Attn: Sandi Sanchez	1
AFCESA/CEXF Attn: Jim Hotell	1	150 Vandenberg St., Suite 1105 Petterson AFB, CO 80914-4150	
139 Bames Drive, Suite 2 Tyndall AFB, FL 32403-5323		HQ AMC/CEOO Attn: Duane Morgan	1
WR-ALC/LVV Attn: Sharon Edwards & Mary Zampa 225 Ocmulgee Court	2	507 A Street Scott AFB, IL 62225-5022	
Robins AFB, GA 31098-1647		HQ USAFA/CEF Attn: Richard Duncan	1
ANG/CEXF 3500 Fetchet Ave. Andrews AFB, MD 20762-5157	1	9224 Airfield Drive Air Force Academy, CO 80840-2080	
HQ ACC/CEXF Attn: Randy Caratachea	1	HQ USAFE/RSIXF Attn: Ray Porter Unit 3050, Box 10	1
129 Andrews St., Suite 102 Langley AFB, VA 23665-2769		APO AE 09094-5010	4
HQ AETC/CEOX Attn: Fire Protection Manager 266 F Street West Randolph AFB, TX 78150-4321	1	HQ PACAF/CEOO Attn: CMSgt Soto 25 E Street, Suite D-306 Hickam AFB, HI 96853-5412	1
HQ AFMC/CEOO Attn: Jim McKay 4225 Logistic Ave., Suite 7 WPAFB, OH 45433-5739	1	Total Copies:	23